DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 10/10/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A, BUILDING 01 - MAIN BUILDING		(X3) DATE SURVEY COMPLETED		
		445270	B. WING		10/10/2019		
NAME OF PROVIDER OR SUPPLIER TENNESSEE VETERANS HOME			STREET ADDRESS, CITY, STATE, ZIP CODE PO BOX 10299 MURFREESBORO, TN 37129				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG		BE COMPLETION		
(K 000)	A Life Safety revisit on 10/10/2019 for a on 08/12/2019. All corrected, and no n	t desk review was conducted all previous deficiencies cited deficiencies have been ew non compliance was s in compliance with all	{K 00	DEFICIENCY)	NATE		

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

TITLE

Facility ID: TN7508

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/15/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING (X3) DATE SURVEY COMPLETED

445270

R WING

08/12/2019

NAME OF PROVIDER OR SUPPLIER

TENNESSEE VETERANS HOME

PO BOX 10299

MURFREESBORO, TN 37129

STREET ADDRESS, CITY, STATE, ZIP CODE

(X4) ID PREFIX

SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)

PREFIX TAG

PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)

(X5) COMPLETION DATE

K 000 INITIAL COMMENTS

Stories: 1

Construction type: II Limited Plans on site Constructed: 1991 Sprinklered: Yes Census: 130

A life safety code survey was conducted by the State of Tennessee Department of Health Division of Health Licensure and Regulations Office of Health Care Facilities, on 08/12/2019. During this life safety survey, Tennessee Veterans Home was found not in substantial compliance with the requirements for participation in Medicare/Medicaid at 42 CFR Subpart 483.70(a), Life Safety from fire, and the related National Fire Protection Association (NFPA) standard 101 (2012 Edition).

K 920 Electrical Equipment - Power Cords and Extens

SS=D CFR(s): NFPA 101

Electrical Equipment - Power Cords and **Extension Cords** Power strips in a patient care vicinity are only used for components of movable patient-care-related electrical equipment (PCREE) assembles that have been assembled by qualified personnel and meet the conditions of 10.2.3.6. Power strips in the patient care vicinity may not be used for non-PCREE (e.g., personal electronics), except in long-term care resident rooms that do not use PCREE. Power strips for PCREE meet UL 1363A or UL 60601-1. Power strips for non-PCREE in the patient care rooms (outside of vicinity) meet UL 1363. In non-patient care rooms, power strips meet other UL standards. All power strips are used with general K 000

K 920

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

Facility ID: TN7508

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a defidiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

eet Page 1 of 3

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/15/2019 FORM APPROVED OMB NO. 0938-0391

CENTERS FOR MEDIC	ARE & MEDICAID SERVICES	7		OMB NO. 0930-039
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/GLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - MAIN BUILDING		(X3) DATE SURVEY COMPLETED
	445270	B. WING		08/12/2019
NAME OF PROVIDER OR SUPPLIER TENNESSEE VETERANS HOME			STREET ADDRESS, CITY, STATE, ZIP CODE PO BOX 10299 MURFREESBORO, TN 37129	
PRECEY (FACH DEFIC	Y STATEMENT OF DEFICIENCIES IENCY MUST BE PRECEDED BY FULL OR LSC IDENTIFYING INFORMATION)	ID PREF TAG		DULD BE COMPLETION
substitute for fi Extension cord immediately up which it was in 10.2.4. 10.2.3.6 (NFPA (NFPA 70), 590 This REQUIRE by: Based on obs maintain the el This deficiency compartments residents, staff The findings in 1. Observation revealed a mu NFPA 99, 10.2 2. Observation revealed a sur in room E21. NFPA 99, 10.2 3. Observation revealed 2 mu nurses station. NFPA 99, 10.2 4. Observation revealed an exprotector in the NFPA 99, 10.2	extension cords are not used as a xed wiring of a structure. Is used temporarily are removed from completion of the purpose for stalled and meets the conditions of A 99), 10.2.4 (NFPA 99), 400-8 D.3(D) (NFPA 70), TIA 12-5 EMENT is not met as evidenced ervations, the facility failed to ectrical equipment. If affects 2 of 10 smoke, with the potential to affect all fand visitors. Included: Is on 08/12/2019 at 10:47 AM, Iti plug adapter in room E21. If (2012 Edition), CMS S&C 14-46 as on 08/12/2019 at 10:47 AM, Iti plug adapter in the east hall		No residents were affect this finding. Multi plug adapter in re E21 was immediately removed. The surge protector in I was immediately removed and replaced with a UL approved power strip. The two multi plug adapthe East nurses station immediately removed. The extension cord local Social services was immediately removed. Maintenance has check rooms to ensure complimite with this finding. Maintenance will continuate monthly rounds the ensure compliance with Electrical equipment pocords and extension confindings will be reported. QA&A for one month.	ed all iance in the country of the c

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PRINTED: 08/15/2019 FORM APPROVED OMB NO. 0938-0391

CENTER	RS FOR MEDICARE	& MEDICAID SERVICES	-		4/11/11	[W21 54	דר פוופערע		
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A BUILDING 01 - MAIN BUILDING				(X3) DATE SURVEY COMPLETED			
		445270	B. WING			08	/12/2019		
NAME OF PROVIDER OR SUPPLIER					ET ADDRESS, CITY, STATE, ZIP CODE				
TENNESSEE VETERANS HOME			PO BOX 10299 MURFREESBORO, TN 37129						
(X4) ID PREFIX TAG	(EACH DEFICIENCY MOST BET RECEDED TO CE		ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	D BE	(X5) COMPLETION DATE		
K 920	Continued From page 2 these deficiencies were identified, and were later acknowledged by the administrator during the exit			920					
	conference on 08/1	12/2019.			æ	9	YEST.		
							8		
					9		Ž.		
	r K								
	Z.						I e		

DEPARTMENT OF HEALTH AND HUMAN SERVICES

PRINTED: 08/15/2019 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/S IDENTIFICATI		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER		IPLE CONSTRUCTION	(X3) DATE SURVEY COMPLETED
		445270	B WING _		08/12/2019
NAME OF PROVIDER OR SUPPLIER TENNESSEE VETERANS HOME				STREET ADDRESS, CITY, STATE, ZIP C PO BOX 10299 MURFREESBORO, TN 37129	
(X4) ID PREFIX TAG	(FACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COI (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	I SHOULD BE COMPLETION
E 000	Initial Comments	<u> </u>	- E 00	00	1
	conducted by the Sof Health Division of Regulation Office on 08/12/2019. Do Preparedness Sur Home was found in the requirements for the requirements of the requiremen	paredness Survey was State of Tennessee Department of Health Licensure and of Health Care Facilities survey uring this Emergency vey, Tennessee Veterans in substantial compliance with or participation in Emergency gulations for Long-Term Care CFR §483.73.	0		
			(4 30)		
	į.				P.
					b.
			£		
				9	

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER/REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk () denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.